



1/8



2/8








Fig. 3

10/519383

3/8



4/8



S

10/519383

5/8




Fig. 8




Fig. 9

6/8




Fig. 10




Fig. 11




Fig. 12

Stand der Technik

10/519383

7/8




Fig. 13




Fig. 14a




Fig. 14b

8/8




Fig. 15




Fig. 16